Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	18	"method fabricating sensor".ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/02/16 08:09
L2	0	"method fabricating capasitive sensor".ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/02/16 08:10
L3		"method fabricating capacitive sensor".ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/02/16 08:10
L4	26	method near3 fabricating near3 capacit\$3 near3 sensor	US-PGPUB; USPAT; USOCR	OR	ON	2005/02/16 08:13
L5	6	method near3 sens\$3 near3 movement near3 (mass or weight)	US-PGPUB; USPAT; USOCR	OR	ON	2005/02/16 08:14